

Measurement functions

Multi-function measurement to meet different measurement needs

 AC/DC Voltage measurement	 AC/DC Current measurement	 Resistance measurement	 Continuity
 Frequency measurement	 Capacitance measurement	 Measurement by diode	 NCV
 Back Light	 Temperature	 Data Hold	 True RMS
 LOW BATTERY INDICATION	 OVER RANGE DISPLAY	 CAT IV 600V	

